Work Order ID 57350  April 6, 2010 8:20:29 AM								Page 1
Item ID: D3591-1 Revision ID: Item Name: Bushing	Accept				i s	etup Star Stop		
<b>Start Date:</b> 06/04/2010 <b>Start Qty:</b> 60.00		Cust Item ID Customer:	) <b>:</b>			·		818    <b>8</b>    <b>8</b>
Approvals: Process Plan: 10-4-04 Date// QC: Date:	Tooling: SPC (Y/N):	Dat		P	R	kun Star Śtoj		
Sequence ID/ Operation Work Center ID Description	Set Up/ Run Hours	Draw Number	Draw Rev.	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
Draw Nbr Revision Nbr  D3591 Rev B  CONVENTIONAL LATTE  Lathe Conv  Memo  Conventional Lathe  1-Turn as per dwg D3591 2-1	0.00 0.00 Deburr		13	(G	5>			

110

QC2- Inspect parts off machine FAI/FAIB

0.00

Quality Control

0.00

120

QC8- Inspect parts - second check

0.00

IF 10/04/14

Memo

Memo

0.00

Quality Control

Dart Aerospace	Ltd
----------------	-----

W/O:			ANGES					
DATE	STEP	PROCEDURE CHANGE			Ву	Date Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
			•					
Part No	:	PAR #:	Fault Cate	egory:	_ NCR: Yes N	No DQA:	Date: _	1
Resolution:								
NCR:		1	WORK ORD	ER NON-CONFORMA	ANCE (NCR)			
DATE	STEP	Description of NC			ion B	Verification	Approval	Approval
	10.2.	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C	Chief Eng	QC Inspector
								-
								1

#### Work Order ID 57350

April 6, 2010 8:20:29 AM



Page 2

Item ID:

D3591-1

Accept



Setup Start

Stop



**Revision ID:** 

Item Name:

Bushing

**Start Date:** 06/04/2010

**Required Date:** 09/04/2010

**Start Qty: 60.00** 

Req'd Qty: 60.00



**Cust Item ID: Customer:** 

Reference:

Process Plan:

QC:

Date:\_\_\_\_\_

Date: Tooling:

SPC (Y/N):

Date:

Draw

Number

Date:

Plan

Code

Draw

Rev.

Run Start

Reject

**Qty** 

Stop



Sequence ID/ **Work Center ID** 

130

Packaging

Packaging

Operation Description

Identify as per dwg & Stock Location:

0.00

Set Up/ **Run Hours** 

Accept

Qty

Reject

Number

Insp.

Stamp

140

QC

Quality Control

QC21- Final Inspection - Work Order Release

0.00

Memo ·

0.00

10-4-16

## **Dart Aerospace Ltd**

W/O:			W	ORK ORDER	CHANGES					<u> </u>
DATE	STEP	PRO	PROCEDURE CHANGE			Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
			<i>*</i> ,							
		·			i					
Part No	:	PAR #:	Fault Cat	egory:	NO	R: Yes	No <b>DQ</b>	<b>\</b> :	Date:	
			Disposition: Q/			_ QA: N/C Closed:				
NCR:		1	WORK ORE	DER NON-CO	NFORMANC	E (NCR	)			
DATE	STEP	Description of NC	Corrective Action Section B			Veriti		ation	Approval	Approval
	0.2.	Section A	Initial Chief Eng			Sign & Date	Section		Chief Eng	QC Inspector
										-
-										
										ļ
										i.

#### **Picklist Print**

April 6, 2010 8:20:33 AM

Work Order ID: 57350

Parent Item:

D3591-1

Parent Item Name:

**Comments:** 

Bushing

IPP A 07.02.01 new issue EC

IPP Rev:B 08-09-10 revB as per dwg DD verified by:EC

**Start Date:** 06/04/2010

Required Date: 09/04/2010

**Start Qty:** 60.00

Required Qty: 60.00

Date

Issued

Component Item ID/ Item Name

M304TR0.500W.035

Replacement Mfg/ Item ID Purch

Purchased

Bin Primary Item Location

No

Last Location Route Seq ID 100

Unit of Qty on Measure Hand 29.6240

Remaining Qty To Pick 22.1053

Qty Issued

Status

Page 1

1 (48) 8811 188 1111 881		ABSTE TIL MAIN LINIBL SILLE COLLI DELL SILLE MICHALINI	
304 RD Tube	500 x	035W	

W	arehouse	Loc Oty	Loc Code
	<b>Location</b>		
Ma	in Warehouse		
	MAT017	29.624	
	112187	4.75	
	112800	24.874	

114356

22.3 DL 10/04/14/

# Dart Aerospace Ltd

W/O:			W	ORK ORDER CHANG	GES				
DATE	STEP	PRO	PROCEDURE CHANGE			Date Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector	
Part No	:	PAR #:	Fault Cate	gory:	_ NCR: Yes	No DQA:	Date: _	<u> </u>	
Resolution:									
NCR:			WORK ORD	ER NON-CONFORM	ANCE (NCR	)			
DATE	STEP	Description of NC	Corrective Action Section B			Verification	Approval	Approval	
DAIL	SIEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C	noc Section C	Chief Eng	QC Inspector
								-	


DART AEROSPACE LTD	Work Order:	57350
Description: Bushing	Part Number:	D3591-1
Inspection Dwg: D3591 Rev: B		Page 1 of 1

### FIRST ARTICLE INSPECTION CHECKLIST

	x	First Artic	<del></del>	_	otype		
Drawing Dimension	Tolerance	Actual Dimension	Accept	Reject	Method Inspecti		omments
Ø0.500	+0.000/-0.002	.500					
Ø0.430	+0.006/-0.001	.430					
4.100	+0.000/-0.005	4.098					
							i.
				_			<u> </u>
			0.0				
easured by:	<del></del>	Audited by:	<u> </u>		Prototype	Approval:	N/A
Date:	10/64/13	Date:	64/14			Date:	N/A
ev Date	Change	/	1			Revised by	Approve
A 08.09.04 B 09.05.07	New Issue Tolerance updated	ner Dwa Rev B	<u> </u>			KJ/DD KJ/EC	<del>                                      </del>

Dart Aerospace
----------------

W/O:			GES							
DATE	STEP	PROC	PROCEDURE CHANGE				Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector	
									- · ·	
		·								
Part No:				NCR: Yes No DQA: Date:						
	R	esolution:	_ Dispositio	n:	QA: N/C Closed: Date:					
NCR:		W	ORK ORD	ER NON-CONFORM	ANCE (NC	<b>?</b> )				
DATE	STEP	Description of NC	Corrective Action Section B			Verific	ation	Approval	Approval	
		Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	🗴   Secti		Chief Eng	QC Inspector	
					,				-	
				-						
			· ·	•						



Dart Aerospace Ltd
--------------------

	•									
W/O:			V	ORK ORDER CHANG	GES					*
DATE	STEP	PRO	OCEDURE CH	CEDURE CHANGE			Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
				NCR: Yes No DQA: Date:						
Resolution:						A: N/C Closed: Date:				
NCR:			WORK OR	DER NON-CONFORM	IANCE (N	ICR)				
DATE	STEP	Description of NC Section A	Corrective Action Section B				Verific	ation	Approval	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng		Sign & Date		Section C		
										-
								:		
				•						
										·
	1		1		1		1		l	l